

TECH BULLETIN: TB 110 Dodge 5.9L & 6.7L Cummins Engine Tech Tips GB P/N: 712-501, 712-502, 712-503, 712-504

IMPORTANT WARRANTY INFORMATION AVOID SEVERE ENGINE DAMAGE & PREMATURE INJECTOR FAILURE

NOTICE: NEW FUEL FILTER ADD ON REQUIRED

GB has released an OE recommended severe duty fuel filter upgrade kit for the Dodge Cummins 5.9L and 6.7L. Contamination is the number one cause of failure on Dodge common rail systems. The original equipment filtration system is inadequate in removing common contaminates, resulting in premature injector failure. Injector failure due to contamination is not covered under GB's limited warranty. This new kit includes an upgraded fuel filter and housing, wiring harness, fuel lines, fuel heater and water-in-fuel sensor (used on 5.9L only).

| Year | Application | GB P/N | Replacement Filter | |
|-----------|----------------------------------|---------|-----------------------|-----|
| 2004.5-09 | Dodge Cummins 5.9L Pickup | 522-050 | 522-056 | |
| 2007-12 | Dodge Cummins 6.7L Pickup | | | |
| 2007-12 | Dodge Cummins Cab & Chassis 6.7L | 522-049 | | TTT |

522-050

SPECIAL INSPECTION PROCEDURE

- Contamination is common in the rail near the #5 and the #6 injection line connections. Remove and inspect the #1 line fitting with a borescope. If any contamination is present, it is mandatory to replace the rail.
- High pressure fuel inlet tube contamination and wear is common, which can result in immediate injector failure upon installation. Failure to replace the fuel inlet tube at the time of injector replacement will void the injector warranty. Use GB part number 522-043 or equivalent.
- Inspect the return back-pressure valve in the injector return line connection banjo bolt for contamination. Clean or replace if needed.
- Inspect the injector bore for corrosion, damage or leakage prior to the installation of the injector.
- Ensure the injector is torqued to the manufacturer's specification.

Injector failure as a result of any of these conditions is not covered by GB's limited warranty. SEE BACK SIDE FOR ADDITIONAL INFORMATION

IMPORTANT WARRANTY INFORMATION AVOID SEVERE ENGINE DAMAGE & PREMATURE INJECTOR FAILURE

SPECIAL 6.7L ENCODING INSTRUCTIONS (P/N: 712-503 & 712-504)


The GB 712-503 & 712-504 injectors are tagged with a six digit alphanumeric code that must be entered into the ECM using a scan tool. The encoding refers to the injectors flow and operating characteristics and is unique to each injector. The ECM uses this code to adjust baseline fuel delivery for each injector and cylinder. It is mandatory to enter the injector's code to achieve proper engine performance.


COMBUSTION SEAL INSTALLATION


Failure to install the copper combustion seal or an improperly torqued injector can result in injector failure and engine damage. The copper combustion seal is included with GB's remanufactured injectors. See figure 1.

Injector failure as a result of this condition is not covered by GB's limited warranty.

- Ensure the copper combustion seal is present on the injector being replaced. If the seal is missing inspect the injector bore for seal and remove prior to installing replacement injector.
- If the injector being replaced shows signs of combustion seal leakage and the prior injector is missing the copper seal it will be necessary to replace the injector sleeve prior to installing the replacement injector. Failure to do so will result in leakage of the new combustion seal and injector failure.
- Always inspect the injector bore for corrosion. damage or leakage prior to installing new injector.







An injector installed without the copper combustion seal will result in hot combustion gases heating the injector's lower section, resulting in premature failure. If combustion gas leakage is present the injector sleeve must be replaced.

SEE FRONT SIDE FOR ADDITIONAL INFORMATION

GB Remanufacturing, Inc.

2040 E Cherry Industrial Circle • Long Beach, CA 90805-4410 Phone: 562-272-7333 • Fax: 562-272-7377 • www.gbreman.com