

### ALWAYS FOLLOW MANUFACTURER'S SERVICE PROCEDURES



**NOTE:** The Fuel Injector Inlet tube for the 5.9L engine has been revised to utilize the larger late model tube that is also used on the 6.7L engine. As a result, the supplied part is the updated design and may not match the appearance of the part being replaced.

If the injector was removed or replaced a special torque procedure needs to be followed in order to ensure proper sealing between the injector and tube. Consult factory service manuals for proper torque and procedures. Failure to properly install tube can result in a no-start or hard-start condition or poor engine performance.

#### GB Remanufacturing, Inc.

2040 E Cherry Industrial Circle • Long Beach, CA 90805-4410  
Phone: 562-272-7333 • Fax: 562-272-7377 • [www.gbreman.com](http://www.gbreman.com)